

Lithonia Lighting CFMK Surface Mount Brackets recalled due to Injury Hazard

Starting date: Posting date: Type of communication: Subcategory: Source of recall: Issue: Audience: Identification number:	August 19, 2020 August 19, 2020 Consumer Product Recall Physical Hazard Health Canada Product Safety General Public (GP) (Generated by system number)	Report a Concern
---	--	--

Affected products	What you should do
-----------------------------------	------------------------------------

Summary

- **Product:** Lithonia Lighting CFMK Surface Mount Brackets
- **Issue:** The bracket can fail to securely surface mount the CPANL LED fixture and allow the fixture to fall unexpectedly, posing a risk of injury.
- **What to do:** Consumers should immediately stop using the recalled product and contact Lithonia Lighting for a free CFMK Bracket repair kit and installation instructions. Consumers should prevent people from going into the immediate area under the fixtures until the brackets are repaired.

Joint Recall

Joint recall with Health Canada, the United States Consumer Product Safety Commission (US CPSC) and Lithonia Lighting

Affected Products

Lithonia Lighting CFMK Surface Mount Brackets

Product Description

This recall involves metal CFMK H-brackets that are screwed into the ceiling and used to surface mount CPANL LED fixtures. The CFMK bracket was included as an optional mounting accessory with 1x4, 2x4 and 2x2 CPANLs.

The following CFMK brackets are included in the recall:

Model Number	Serial Number	Date Code
CPANL 2X2 35K with Bracket	*264JGP	L04xx18-L10xx18 GP07xx18- GP05xx20

CPANL 2X4 35K with Bracket	*264JGN	L04xx18-L10xx18 GP07xx18- GP05xx20
CPANL 1X4 35K with Bracket	*264M17	L04xx18-L10xx18 GP07xx18- GP05xx20
2X2CFMK	*2518HR	GP11xx18-GP05xx20
2X4CFMK	*2518HU	GP11xx18-GP05xx20
1X4CFMK	*2518HL	GP11xx18-GP05xx20

Hazard Identified

The CFMK bracket can fail to securely surface mount the CPANL LED fixture and allow the fixture to fall unexpectedly, posing a risk of injury.

As of August 13, 2020, the company has received 2 reports of failing brackets in Canada, and no reports of injury. In the United States, the company has received 22 reports of failing brackets, and 1 report of minor injury.

Number Sold

Approximately 11590 units of the affected product were sold in Canada, and approximately 318,000 were sold in the United States.

Time Period Sold

The affected products were sold from August 2018 to June 2020.

Place of Origin

Manufactured in China.

Companies

Distributor

Lithonia Lighting, a division of Acuity Brands Lighting, Inc.
Conyers
Georgia
UNITED STATES

Manufacturer

Xiamen Guangpu Electronics Co., Ltd (Gopro)
Xiamen
Fujian
CHINA

Manufacturer

Lextar Electronics Corp.
Hsinchu
Taiwan
REPUBLIC OF CHINA

What you should do

Consumers should immediately stop using the recalled product and contact Lithonia Lighting for a repair kit and installation instructions. Consumers should prevent people from going into the immediate area under the fixtures until the brackets are repaired.

For more information, consumers can contact Lithonia Lighting by telephone toll-free at 1-855-307-2454 from 8:00 a.m. to 5:00 p.m. EST, Monday to Thursday, or visit the [company's website](https://lithonia.acuitybrands.com/) (https://lithonia.acuitybrands.com/) to order a free repair kit.

Consumers may view the release by the US CPSC on the [Commission's website](#) (US CPSC to provide link).

Please note that the Canada Consumer Product Safety Act prohibits recalled products from being redistributed, sold or even given away in Canada.

Health Canada would like to remind Canadians to report any health or safety incidents related to the use of this product or any other consumer product or cosmetic by filling out the [Consumer Product Incident Report Form](https://www.canada.ca/en/health-canada/services/consumer-product-safety/advisories-warnings-recalls/report-incident-involving-consumer-product.html) (https://www.canada.ca/en/health-canada/services/consumer-product-safety/advisories-warnings-recalls/report-incident-involving-consumer-product.html).

This recall is also posted on the [OECD Global Portal on Product Recalls website](http://globalrecalls.oecd.org/) (http://globalrecalls.oecd.org/). You can visit this site for more information on other international consumer product recalls.

Images

Image 1. 1x4 CFMK Bracket



Image 2. 2x2 CFMK Bracket




Image 3. 2X4 CFMK Bracket

Date modified: (Automatically generated date)



[Terms and conditions](#) | [Transparency](#)

About us

[Health Canada](#)
[Public Health Agency of Canada](#)
[Canadian Food Inspection Agency](#)
[Transport Canada](#)

Contact us

[Report safety concerns](#)
[Public involvement](#)

Stay connected

[Facebook](#)
[Share](#)
[Mobile application](#)
[Subscribe](#)
[Video Gallery](#)

Browse by

[Age](#)
[Audience](#)

HEALTH
[healthycanadians.gc.ca](#)

TRAVEL
[travel.gc.ca](#)

SERVICE CANADA
[servicecanada.gc.ca](#)

JOBS
[jobbank.gc.ca](#)

ECONOMY
[actionplan.gc.ca](#)

Canada.gc.ca